

Docket No.: MP1483 (PATENT)

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of: Daniel Yellin

Patent No.: 7,428,260

Issued: September 23, 2008

For: UNIFIED MMSE EQUALIZATION AND MULTI-USER DETECTION APPROACH FOR USE IN A CDMA SYSTEM

### REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Attention: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected.

In the Application		In the Patent		Error				
In the Drawings:								
Sheet	Figure	Sheet	Figure					
Replacement	2	2	2	PTO				
Drawings								
August 9, 2007								
Sheet 2								
In the Specification:								
Page	Line(s)	Column	Line(s)					
8	15	4	57	PTO				

Patent No.: 7,428,260 Docket No.: MP1483

8	21		4	64	PTO
8	26		5	5	PTO
8	27		5	6	PTO
8	29		5	9	PTO
9	7		5	20	PTO
14	23		8	40	Applicant
15	17		8	65	PTO
18	15		11	5	PTO
18	24		11	15	PTO
21	13		13	10	PTO
21	14		13	11	PTO
21	15		13	15	PTO
22	3		13	34	PTO
22	7		13	40	PTO
24	27-28		15	17-18	PTO
In the Claims:					
Amendment	Claim	Line	Column	Line	
August 9, 2007	32	9	19	21	Applicant
Page 9					

Two of the errors were found in the application or an amendment as filed by Applicant. Our check in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a) is enclosed.

With regard to Sheet 2, Fig. 2 in the drawings, it appears that the Office published the annotated sheet instead of the replacement sheet submitted with the Amendment dated August 9, 2007.

The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

Patent No.: 7,428,260 Docket No.: MP1483

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 13-2855, under Order No.

31146/MP1483.

Dated: December 1, 2008

Respectfully submitted/

Gregory E. Stanton

Registration No.: 45,127

MARSHALL, GERSTEIN & BORUN LLP 233 S. Wacker Drive, Suite 6300

Sears Tower

Chicago, Illinois 60606-6357

(312) 474-6300

Attorney for Applicant

PTO/SB/44 (09-07)

Approved for use through 08/31/2010. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1690)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_3

PATENT NO. : 7,428,260

APPLICATION NO. : 10/697,853

ISSUE DATE : September 23, 2008

INVENTOR(S) : Daniel Yellin

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

#### In the Specification:

At Column 4, line 57, "g1(t)" should be -- g(t) --.

At Column 4, line 64, "a1(t)" should be -- a1(t) --.

At Column 5, line 5, "g1(t)" should be -- g(t) --.

At Column 5, line 6, "g1(t)" should be -- g(t) --.

At Column 5, line 9, "Further-more" should be -- Furthermore --.

At Column 5, line 20, " $\forall k_1k_2$ " should be --  $\forall k_1 \neq k_2$  --.

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1950)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 2 of 3

At Column 8, line 40, "in-fact" should be -- in fact --.

At Column 8, line 65, "MM" should be -- MAI --.

At Column 11, line 5, " $g_1(t)$ " should be --  $g_i(t)$  --.

At Column 11, line 15, " $g_1(t)$ " should be --  $g_i(t)$  --.

At Column 13, line 10, "h1(t)" should be -- h(t) --.

At Column 13, line 11, " $h_1(t)$ " should be --  $h_i(t)$  --.

At Column 13, line 15, "h1(t)" should be -- h(t) --.

At Column 13, line 34, "h<sub>1</sub>(t)" should be -- h<sub>i</sub>(t) --.


At Column 13, line 40, "g1(t)" should be -- g(t) --.

At Column 15, lines 17-18, "chip-rate 1=1 equalizer" should be -- chip-rate equalizer --.

#### In the Claims:

At Column 19, line 21, "MUD\_type" should be -- MUD-type --.

collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)



MAILING ADDRESS OF SENDER (Please do not use customer number below): Gregory E. Stanton

MARSHALL, GERSTEIN & BORUN LLP 233 S. Wacker Drive, Suite 6300

Sears Tower